

**SOFTWARE RELEASE NOTE**

**PDL DriveLink 0407AA Version 2.0**

**By: Mark Malone**  
**Title: Software Engineer**  
**Date: 1/03/99**

**Checked: AW**

**Approved: ML**

**PDL DriveLink Version 2.0 Software Release**

This release note covers the release of the software PDL DriveLink.

PDL DriveLink V2.0 software covers the following product ranges:

All Microdrive Elites.

**Changes from Previous Version Software:**

1. Completely new package.
2. Removed support for drive parameter modification and monitoring (EDS functions). This will now be done by a new version of DriveComm.
3. Simplified user interface.
4. Added bootstrap loading of system code into an Elite.
5. General improvements in speed, especially download time.
6. 32 bit operating systems only. DriveLink 2.0 can not be run in Windows 3.1.

**Upgrading From Previous Version Software:**

Installation and upgrade of this product are the same.

Run 0407AA20.EXE self-extracting installation file.

Windows NT 4 requires Service Pack 4 or administrator rights.

New part numbers are as follows:

No. 0407AA20