

1

2

3

4

A

A

B


B

C

C

D

D



DRIVE PANEL TO MOUNTED TO BACK PANEL. ENSURE WHEN MOUNTING THERE IS SUFFICIENT CLEARANCE FOR MOTOR AND SUPPLY CABLES AT THE BOTTOM OF ENCLOSURE. A MINIMUM OF 8 INCHES SHOULD BE LEFT AT TOP OF PANEL TO ALLOW STACK FANS TO PROPERLY VENT.

ISS	DATE	APPROVED

Bardac

40 Log Canoe Circle, Stevensville, MD 21666
 phone (410) 604-3400 fax: (410) 604-3500
 email: info@bardac.com

SHT. TITLE	EXTERNAL STACK PANEL OUTLINE	CUST.	ANY CUSTOMER	DRN.	ENGINEER	DWG. NO.	HJ
DWG. TYPE	PANEL ASSEMBLY DIAGRAM	DIST.		DESIGN	ENGINEER	DWG. ISS.	PRE
JOB TITLE	950A DRIVE PANEL	P.O.		SCALE	10:1	JOB NO.	N/A
LOCATION				SIZE	A	SHT.	1 OF 1

1

2

3

4